

Volkswagen ID.4


Pro Performance Pro Performance 152 kW (77 kWh)


Electric - Automatic - 128659km - 07/2022 Ref 71976











All images

Volkswagen ID.4

Pro Performance Pro Performance 152 kW (77 kWh)

Electric - Automatic - 128659km - 07/2022 Ref 71976

Description

Make	Volkswagen
Model	ID.4
Description	Pro Performance Pro Performance 152 kW (77 kWh)
Mileage	128659 km
Type	Passenger car
Body type	SUV / Off-Road
Doors	5
Seats	5
Exterior color	Black
Interior color	Other
Upholstery	Other

Technical

Fuel type	Electric		
Gearbox	Automatic	Gears	0
Cylinder capacity	0 cc	Cylinders	0
Power KW	152 kw	Horse power	207 hp
Drive train	Rear		

Dimensions

Volkswagen ID.4

Pro Performance Pro Performance 152 kW (77 kWh)

Electric - Automatic - 128659km - 07/2022 Ref 71976

Registration and Warranty

First Registration	12-07-2022
Warranty start	12-07-2022

Options

Comfort

- Start and entry keyless
- Automatic climate control
- Head-up display

Safety

- Lights LED
- Parking assist camera
- Speed limit control system
- Lane departure warning system

Extras

- Heat pump

Volkswagen ID.4

Pro Performance Pro Performance 152 kW (77 kWh)


Electric - Automatic - 128659km - 07/2022 Ref 71976


Equipment


LED headlamps	Augmented reality head-up display
Rear view camera system	Keyless locking and starting system
Energy-efficient heat pump	Lane Assist
Speed Limiter - ACC on Demand	Air conditioning system Climatronic


Image gallery










WESSLING
ID.4


11:51
29.0°C
Fahrzeug
Daten
Fahrzeugstatus
Service
Reifendruck
3 Meldungen
128659 km
OFF
110
0
READY
80 km
D / B
N
R
OK
VIEW



11:49








11:50
28.5°c
2
Ziele
Karte
Bitte laden Sie Ihr Fahrzeug. Sie können nach einer Ladestation in der Nähe suchen.
Abbrechen
Suchen
Keine Zielvorschläge vorhanden.
OFF
Setup


Service
Scheibenwischer in Serviceposition
Inspektion seit
32 Tagen
OFF




Quality
DEKRA
DEKRA


DEKRA
DEKRA
DEKRA
WESSLING
Quality of Life



DEKRA



DEKRA



110
50
km/h
0
PARK
16%
80 km
0
km
0:04
h
41.6
kWh/100km
6
km/h
Ab Start
D / B
N
R


11:54
29.0°C
2
3 Meldungen
3 / 3
Elektrosystem funktioniert nicht richtig. Bitte Werkstatt aufsuchen.
OFF
MENU
CLIMA
ASSIST
MODE















DEKRA
DEKRA
DEKRA

DEKRA
DEKRA
DEKRA


DEKRA


DEKRA
10 cm























wagen Zentrum Essen



